

**CHANGES TO THE DRAWING:**

Fig. 3 has been amended to replace the erroneous reference number "76" with the correct reference number "46."

A replacement sheet with the corrected Fig. 3 is attached.

O I P E

AUG 27 2004

## Replacement Sheet

Title: LOUDSPEAKER DRIVER

Inventor(s): Andreas BUOS et al.

Appl. No.: 09/986,115

Fig 3




Fig 5

